

MEMO TO FILE

On Monday morning, January 14, 1991, Gene Pabst and I checked manholes in the area around the Townhouse and got the following readings:

Wye map J 3:
MH 37 0% L.E.L.
MH 35 0% L.E.L.
MH 74 0% L.E.L.
MH 73 0% L.E.L. (opened cover and sniffed ust sewer odor)
MH 38 0% L.E.L. (opened cover and sniffed ust sewer odor)
MH 41 0% L.E.L.
Wye map -13:
MH 49 0% L.E.L. (opened cover and sniffed, ust sewer odor)
MH 50 0% E.L.

At 1:30 p.m., I returned to the area and checked the manholes again. I got the following readings:

Wye map J-13:
MH 37 0% L.E.L.
MH 35 0% L.E.L.
MH 74 0% L.E.L.
MH 73 0% L.E.L.
MH 38 0% L.E.L.
MH 41 0% L.E.L.

Wye map H-13:
MH 49 0% L.E.L.
MH 50 0% L.E.L.

At 2:00 p.m., I talked to Rick Henry at Toomb's and Company at 1900 E. Dale. He said they didn't use gasoline in any of their building processes, and only had two or three small cans of it that they kept in a storage shed. It rained Monday evening.

On Tuesday morning, January 15, 1991, it was raining ghtly Gene and I checked the following manholes:

Wye map J-13:
MH 73 0% L.E.L.
MH 38 0% L.E.L.
MH 41 0% L.E.L.
Wye map H-13:
MH 49 0% L.E.L.
MH 50 0% L.E.L.

On Wednesday afternoon January 16, 1991, I checked the following manholes:

930

N.

GLENSTONE

Wye map J-13:

MH 73 0% L.E.L

MH 38 0% L.E.L

MH 41 0% L.E.L

Wye map H-13:

MH 49 0% L.E.L

MH 50 0% L.E.L

On Friday morning January 18 99 I checked the following manholes:

Wye map -13:

MH 37 0% L.E.L

MH 35 0% L.E.L

MH 38 0% L.E.L opened cover and sniffed just sewer odor)

MH 73 0% L.E.L.

MH 74 0% L.E.L.

MH 41 0% L.E.L.

Wye map H-13:

MH 49 0% L.E.L.(opened cover and sniffed just sewer odor)

MH 50 0% L.E



Karen Chandler

WPCI II

S & E

cc Mr Steve Meyer, P.E., Sanitary Engineer
Mr Randy Lyman, Sewer Surveillance & Billing Supervisor